



## To Unload panels from the crate follow these steps:

Lift only one side of the panel slowly with the other edge of the panel resting on the crate/flat surface.

Lift it off the crate/flat surface, put a hand underneath and carry with the profile placed vertically (Figure 1).

To put the panel on the ground let it rest on the long edge first and slowly put it on the ground.

Always keep the panel upright or on its edge when carrying to avoid breakage

Never carry the panel flat, it will snap in the middle.



## Storage

Stonini panels need to be stored on a flat surface in the dry area. Stacking is allowed however no more than 8-10 panels at the time should be stored (profile depending). Sheets of polystyrene or protective foam should be placed between panels.

## Cleaning

For general care and maintenance most spills or marks can be cleaned using plastic brush water or mild detergents. Do not use coloured rugs or solvent-based cleaners.